


Harrison M250

280mm (11in) swing centre lathe



H
Harrison

machine manual

Contents

	Page No.
Summarised Specifications	2
Installation	
1) General arrangement and foundation plan	4
2) Installation instructions	5
3) Lubrication diagram	8
Operation	
1) Controls diagram	10
2) Operating instructions	11
3) Lathe safety	15
Maintenance	
1) Maintenance instructions	18
Parts Section	
1) Parts ordering procedure	23
2) Illustration contents list	24
3) Spare parts illustrations	25
4) Standard/Proprietary parts code list	58
Electrical Wiring Diagram	61

Machine Specification

280mm (11in) swing Centre Lathe

500mm MODEL – 500mm (20 in) between centres
 750mm MODEL – 750mm (30 in) between centres

This machine is manufactured to British metric standards throughout, and is available in two bed lengths

Metric or English gear boxes and drive screws (together with the appropriate micrometer dials) are optional variations.

summarised specification

Centres	Height	145mm (5.7 in)	English Gearbox with 4 TPI Leadscrew	
	Admits Between	500mm (20 in) or 750mm (30 in)		
Swing	Over Bed	280mm (11 in)		Threads English Pitches (56) 4 - 84 TPI
	Over Cross Slide	178mm (7 in)		Metric Pitches (23)* 0.4 - 10mm
Spindle	Bored to Pass	35mm (1.375 in)		<i>*(available by changewheels supplied as additional equipment)</i>
	Nose	D1-3		Feeds Longitudinal (24) . . . 0.0006 - 0.016 in
	Morse Taper In Nose Bush	3		Cross (24) . . . 0.0003 - 0.008 in
Speeds	Number	9		Bed
	50 Hz	Range 40 - 1500 rpm		
Machines	Motor	0.9 kW (1.2hp)		Depth Under Headstock 230mm (9 in)
	or	Range 80 - 3000 rpm	Cross Slide	
or	Motor 1.3 kW (1.8hp)	Width 130mm (5.1 in)		
60 Hz	Range 40 - 1500 rpm	Motor (Single Phase) 1.1 kW (1.5hp)	Travel 165mm (6.5 in)	
	Motor 1.5 hp		Top Slide	
or	Range 52 - 2000 rpm	Width 76mm (3 in)		
Machines	Motor 1.5 hp	Motor (Single Phase) 1.5 hp	Travel 92mm (3.6 in)	
	or		Range 52 - 2000 rpm	Tailstock
or	Motor (Single Phase) 1.5 hp	Quill Diameter 38mm (1.5 in)		
Leadscrew	Diameter 25mm (0.98 in)	Thread 6mm pitch or 4 TPI	Travel 95mm (3.7 in)	
	Metric Gearbox with 6mm pitch Leadscrew		Weight	
Threads Metric pitches (33) 0.25 - 8mm		500mm (20 in) Centres. . . .356 kg (785 lbs)		
English Pitches (33)* 3 - 72 TPI		750mm (30 in) Centres. . .457 kg (1008 lbs)		
<i>*(available by changewheels supplied as additional equipment)</i>		Shipping Data	Gross Weight Packing Case Dimensions	
Feeds Longitudinal (21)0.012 - 0.4mm				L W H
Cross (21) 0.006 - 0.2mm		500mm (20 in) Centres		
		457 kg (1008 lbs) . . 1574 x 838 x 1371mm		
		(62" x 33" x 54")		
		750mm (30 in) Centres		
		559 kg (1232 lbs) . . 1828 x 838 x 1371mm		
		(72" x 33" x 54")		


standard equipment

Single Toolpost
 Work Driver Plate
 No. 5/3 Morse Centre Bush
 2 No. 3 M.T. Centres

Spanners, Keys and Oil Gun
 Machine Manual
 & Standard Inspection Certificate

Illustrated or specified data is not binding in detail: The manufacturers reserve the right to modify design, specification and price without notice.

Installation



735mm

1625mm
1375mm

750mm
500mm

178mm
280mm

1080mm

165mm

370mm
365mm

440mm
187mm

40mm

40mm

1250(750mm cts m/c)
1000(500mm cts m/c)

155mm

Lifting

The approximate weights of the machine are:-

500mm Model (500 mm/20") between centres - 400 kg (880 lbs)

750mm Model (750 mm/30") between centres - 460 kg (1010 lbs)

The machine should be lifted using a rope sling looped under both ends of the swarf tray.

Cleaning

Bright surfaces are coated with an anti-corrosive compound at despatch and this must be completely removed using White Spirit or Paraffin (Kerosene) before operating the controls or moving the slides. **DO NOT USE CELLULOSE SOLVENTS.** Oil the bright surfaces and slideways **AFTER CLEANING.** (see Lubrication diagram).

Positioning

Locate the machine on a solid foundation allowing sufficient area for operation and maintenance access. (SEE GENERAL ARRANGEMENT AND FOUNDATION PLAN).

The lathe may be used when free standing, but for maximum performance it should be bolted down.

- (1) **Free standing.** Position the machine on its foundation and adjust each of the four levelling screws to take an equal share of the weight. Then using an engineer's precision level on the bedways make further adjustments for level conditions.
- (2) **Fixed installation.** Position the machine over four 12 mm (1/2") diameter foundation bolts, set to suit the base. (SEE GENERAL ARRANGEMENT AND FOUNDATION PLAN).

Accurately level the machine as in (1), then tighten the foundation bolts evenly to avoid distortion and finally re-check for level conditions.

Electrical Supply

Power should be supplied through an external fused isolator - recommended fuses being 15 amp for 220 volts supply and 10 amp for 380 to 440 volts supply. External wiring should be of a permanent character and be undertaken by a competent electrician. SEE GENERAL ARRANGEMENT AND FOUNDATION DRAWING FOR CABLE ENTRY.

Line connections and a substantial earth continuity conductor should be connected to the terminal block (SEE ELECTRICAL WIRING DIAGRAM).

If main spindle rotation does not coincide with that indicated by forward/reverse switch at control station, interchange two line connections.

continued

Lubrication (Refer to Lubrication diagram)

Ensure that the headstock, gearbox and apron are filled to the level of the relevant oil sight windows - and oil the cross-slide nut, dials and changewheel stud etc. through the appropriate oil nipples using the oil gun provided.

Running-in


For optimum bearing life and performance it is recommended that high spindle speeds be avoided during the initial life of the machine.

Alternatively a running-in procedure should be adopted as follows: -

Make a low feed rate selection and run the machine light for 3 hours at 260 rpm
then for 1 hour at 550 rpm
then for ½ hour at 750 rpm

Lubrication


Check levels and oil daily
 Schauglas und Öl täglich überprüfen
 Vérifier les regards et graisser quotidiennement



-
-
-
-

Mobil	BP	Castrol		Esso	Shell	TEXACO
DTE OIL HEAVY MEDIUM	ENERGOL HLP 68 (ISO)	HYPIM AWS 68	P.W.L.C.	NUTO H68	TELLUS 68 OR R68	RANDO HD 68
DTE EXTRA HEAVY	ENERGOL HP 150 (ISO)	ALPHA ZN 220	WLM	NURAY 100	VITREA 220	REGAL R & O 220

Operation



- | | | |
|------------------------------|--|-------------------------------------|
| 1. MAINS ISOLATOR | 9. SPEED SELECTOR LEVER | 17. TAILSTOCK SET-OVER SCREW |
| 2. FORWARD/REVERSE SWITCH | 10. SPEED RANGE SELECTOR DIAL | 18. CARRIAGE LOCK |
| 3. COOLANT ON/OFF SWITCH | 11. TOP SLIDE LOCK | 19. CROSS TRAVERSE HANDLE |
| 4. EMERGENCY STOP PUSHBUTTON | 12. TOP SLIDE TRAVERSE HANDLE | 20. TREADCUTTING ENGAGEMENT |
| 5. START PUSHBUTTON | 13. QUILL LOCK | 21. FEED AXIS SELECTOR |
| 6. FEED SELECTOR | 14. TAILSTOCK CLAMP | 22. FEED ENGAGE |
| 7. FEED SELECTOR | 15. QUILL TRAVERSE HANDWHEEL | 23. LONGITUDINAL TRAVERSE HANDWHEEL |
| 8. FEED DIRECTION SELECTOR | 16. CROSS-SLIDE LOCK (in R.H. side of cross slide) | |

Starting the Machine

1. Ensure that lubrication has been carried out in accordance with the Lubrication diagram.
2. Check that the feed engage lever (22) and thread-cutting lever (20) are in the disengaged positions and that the changewheel cover is firmly secured in place.
3. **Select** - Feed Axis - i.e. cross or longitudinal by means of the apron push-pull knob (21).
Select - Direction of feed - by means of the headstock lower selector (8)
Select - Feed Rate - by referring to the charts on the headstock and selecting (in the sequence listed) the appropriate positions on the gearbox selectors (6) and (7). (Engagement of the feed gears may be assisted by turning the main spindle)
Select ** Spindle speed by turning the speed range selector dial (10) to present the appropriate range i.e. A B or C, then turn the speed selector lever (9) to point to the required speed from the chart.
(Engagement of the drive gears may be assisted by manually turning the spindle)
4. Switch on the electrical supply at the mains isolator (1) which is the red knob at the L.H. end of control station.
5. Select direction of spindle rotation by means of forward/reverse switch (2).
6. Start the spindle by means of start push-button (5).
7. Start and stop the feed motion as required by means of the feed engage lever (22)

Stopping the Machine

The machine may be stopped by the Emergency Stop pushbutton (4).

Operational Notes

FACEPLATES

NOTE MAXIMUM SPEEDS:-

1500 rpm for 260 mm (12") dia.

COARSE SCREWCUTTING/
FEED RANGE 'J'

SHOULD NOT BE USED WITH
SPINDLE SPEEDS ABOVE 750 RPM.

NOTES

** See Installation instructions (RUNNING-IN) if starting the machine for the first time.

continued

Operational notes continued

Micrometer dials are direct reading (for work piece diameter reduction on the cross-slide) and are of the friction-grip type for easy index settings.

Longitudinal traverse handwheel (23) may be disengaged by pulling it away from the apron face.

Tailstock set over adjustment - is provided in the form of socket screws (17) mounted in each side of the tailstock body, - a similar but 'location-screw' is fitted in the rear face of the body.

Set-over adjustment is made as follows: -

Unclamp the tailstock - (lever 14)

Slacken the rear 'location-screw' (say one half turn)

Then - Alternatively slacken one set-over screw and tighten the other until the required setting is achieved.

Tighten the rear 'location-screw'

And Re-clamp the tailstock.

Leadscrew Drive

Drive to the leadscrew is obtained by first removing the torque limiter cover plate. Then slide the driving sleeve towards the gearbox so engaging the shear pin with the leadscrew shaft. When not in use it is recommended that the leadscrew be disengaged.

MOUNTING OF CHUCKS, FACEPLATES and other SPINDLE MOUNTED ATTACHMENTS.

Ensure that the location faces on both nose and attachment are scrupulously clean.

Check that all the cams are in the release position (Fig. 1).



Mount the attachment on to the spindle nose and lock each cam by turning it clockwise using the key provided.

A reference line R1 (Fig. 1) should be scribed on each chuck or faceplate to coincide with the reference line R on the spindle nose. This assists subsequent re-mounting

NOTE:-

For correct locking conditions each cam must tighten with its index line between the two vee marks on the nose (Fig. 2).

DO NOT INTERCHANGE CHUCKS OR OTHER SPINDLE MOUNTING ITEMS BETWEEN LATHES WITHOUT CHECKING EACH CAM FOR CORRECT LOCKING.



TO ADJUST 'CAMLOCK STUDS'


Remove Lockscrew (B).

Turn Stud (A) one full turn, in or out as required.

Re-fit and tighten lockscrew (B).

NOTE:-

A datum ring (C) is marked on each stud as a guide to the original or initial setting.



Spindle Nose

(A) METRIC THREADS on METRIC LEADSCREW MACHINES
or
ENGLISH THREADS on ENGLISH LEADSCREW MACHINES

For these threads it is recommended that the "thread indicator dial" be used - this allows the leadscrew nuts to be disengaged at the end of each screwcutting pass, provided that they are re-engaged in accordance with the chart mounted on the front face of the dial unit.

METRIC LEADSCREW MACHINES
(METRIC THREADS ONLY)

The chart shows:-

in column 1. mm pitch to be cut.

in column 2. (✱) The requisite gear of the double pinion should be arranged to mesh with the leadscrew.


in column 3. The dial numbers at which the leadscrew nuts may be engaged.


ENGLISH LEADSCREW MACHINES
(ENGLISH THREADS ONLY)

The chart shows:-


in column 1. T.P.I. to be cut.

in column 2. Dial numbers at which the leadscrew nuts may be engaged.



 mm

0.25	20	14	✱	1.4	21	135
0.3	20	14		1.5	20	14
0.35	21	135		1.75	21	135
0.4	20	14		2	20	14
0.5	20	14		2.5	20	14
0.6	20	14		3	20	14
0.7	21	135		3.5	21	135
0.75	20	14		4	20	14
0.8	20	14		5	20	14
1	20	14		6	20	14
1.2	20	14		7	21	135
1.25	20	14		8	20	1

 ins

4	1-6	11	1-6	28	1-6
4½	135	12	1-6	30	1-6
5	1-6	14	1-6	32	1-6
5½	135	15	1-6	36	1-6
6	1-6	16	1-6	38	1-6
6½	135	18	1-6	40	1-6
7	1-6	19	1-6	44	1-6
7½	135	20	1-6	48	1-6
8	1-6	22	1-6	52	1-6
9	1-6	24	1-6	54	1-6
9½	135	26	1-6	56	1-6
10	1-6	27	1-6	60	1-6

(B) ENGLISH THREADS on METRIC LEADSCREW MACHINES
or
METRIC THREADS on ENGLISH LEADSCREW MACHINES
or
ALL THREADS ON MACHINES NOT FITTED WITH THREAD INDICATOR


For these threads the leadscrew nuts are kept engaged throughout the cutting of any one thread. This involves reversing the whole drive by means of the reverse switch (2) at each end of the screwcutting pass whilst at the same time relieving or increasing the cut as required.

(Threads 'A' may also be cut by this method).

Thread – cutting


CHANGEWHEEL COMBINATIONS

Fig. 2A for Metric Leadscrew Machines



6 mm. pitch Leadscrew


Fig. 2B for English Leadscrew Machines





4 tpi. Leadscrew

THREADCUTTING — METRIC GEARBOX



STANDARD THREADS AVAILABLE



 mm									
0.25	N3F	0.7	M1F	1.2	K1G	2	L2G	3.5	M2H
0.3	K3F		M3G		K3H		N1H	4	L2H
0.35	M3F	0.75	K2F	1.25	N2G		N3J		N1J
0.40	L3F	0.8	L1F	1.4	M1G	2.4	K1H	4.8	K1J
0.5	N1F		L3G		M3H		K3J	5	N2J
	N3G	0.875	M2F	1.5	K2G	2.5	N2H	5.6	M1J
0.6	K1F	1	L2F	1.6	L1G	2.8	M1H	6	K2J
	K3G		N1G		L3H		M3J	6.4	L1J
0.625	N2F		N3H	1.75	M2G	3	K2H	7	M2J
						3.2	L1H	8	L2J
							L3J		

THREADS AVAILABLE WITH ADDITIONAL CHANGEWHEELS

 ins					
		W	X	Y	Z
72	N3	30	81	40	84
64	N3	35	84	40	84
56	N3	40	84	40	84
48	N3	40	84	40	72
40	N3	22	88	80	63
36	N3	30	81	60	63
32	N3	35	84	60	63
28	N3	30	84	80	63
27	N3	30	81	80	63
26	N3	30	78	80	63
25	L3	22	88	80	63
24	N3	35	84	80	63
23	N3	40	92	80	63
22	N3	40	88	80	63
20	K3	35	84	80	63
19	N3	40	76	80	63
18	N3	40	72	80	63
16	N2	22	88	80	63
14	N1	30	84	80	63
13	N1	30	78	80	63
12	N1	35	84	80	63
11.5	N1	40	92	80	63
11	N1	40	88	80	63
10	K1	35	84	80	63
9	N1	40	72	80	63
8	K2	35	84	80	63
7.5	L1	35	84	80	63
7	L2	30	84	80	63
6	L2	35	84	80	63
5	K1	60	72	80	63
4.5	L2	40	72	80	63
4	K2	60	72	80	63
3	L2	60	72	80	63

993

				
MOD		X	Y	Z
.3	K3	22	88	56
.4	L3	22	88	56
.5	N1	22	88	56
.6	K1	22	88	56
.7	M1	22	88	56
.8	L3	44	88	56
1	N1	44	88	56
1.25	N2	44	88	56
1.5	K2	44	88	56
1.75	M2	44	88	56
2	L2	44	88	56
2.5	N2	44	88	28
3	K2	44	88	28
3.5	M2	44	88	28

					
DP		W	X	Y	Z
56	N3	44	98	100	63
48	N3	44	84	100	63
40	N3	55	81	72	49
36	N3	44	81	100	49
32	N3	55	56	80	63
28	N3	55	63	80	49
24	N3	55	63	80	42
22	N3	60	63	80	42
20	K3	55	63	80	42
18	N1	44	81	100	49
16	N2	44	63	80	56
14	N1	55	63	80	49
12	N1	55	63	20	42
11	N1	60	63	80	42
10	K1	55	63	80	42
9	L2	44	81	100	49
8	K2	55	63	80	42

1037

Lathe Safety

Every effort has been made in the design and production of the M250 lathe to comply with statutory safety requirements and to provide a fundamentally safe machine tool. Its safety features include:-

Covered leadscrew

Torque limiter on Feed Shaft

Fail-Safe switch operates if End Guard removed.

Shear Pin for leadscrew

Interlock in Apron prevents simultaneous engagement of feed shaft and leadscrew.

In the further interests of safety, attention should be given to the following notes:-

A. Machine Capacity

The dimensions of a component which can be accommodated on the M250 lathe are limited only by the physical restrictions of the machine itself but responsibility for the following points with respect to machining a component must inevitably rest with the user.

- (1) Ensuring that the operator has had suitable training and possesses the required degree of skill and experience to undertake the work.
- (2) Providing suitable work holding and/or supporting equipment, i.e. chucks, steadies, revolving centres, etc.
- (3) Ensuring that suitable tooling is provided and correctly mounted.
- (4) Ensuring that suitable feeds and speeds are selected (if in doubt select the lowest).
- (5) Providing suitable workpiece guards and ensuring that these are consistently used.

B. Lathe Safety Rules

- (1) Read and understand operation notes before attempting to use the machine.
- (2) Keep lathe work areas clean.
- (3) Keep area surrounding machine tidy.
- (4) **ENSURE YOU KNOW HOW TO STOP THE MACHINE BEFORE STARTING IT.**
- (5) Do not interchange chucks or other spindle mounting items between lathes without checking for correct locking (see operational notes).
- (6) Use only 'high speed' chucks.
- (7) Note maximum permissible speeds of faceplates (see operational notes).
- (8) Remove chuck key immediately after use.
- (9) Check load capacity of revolving centres.
- (10) Ensure workpiece guards are in position before starting machine.
- (11) **Do not** use cracked or chipped tools.
- (12) Check —
 - Spindle speed selected.
 - Feed rate selected.
 - Direction of feed, and that
 - Feed & thread cutting levers are disengaged before starting the spindle.
- (13) **STOP MACHINE IMMEDIATELY ANYTHING UNEXPECTED HAPPENS.**
- (14) Do not use coarse feed range on high spindle speeds (see operational notes).
- (15) **Do not** change spindle speeds when spindle is rotating.
- (16) **Do not** touch revolving chuck, spindle, or workpiece.
- (17) **Do not** remove work from the machine without retreating the tool to a safe position.
- (18) Stop motors and switch off isolator when leaving machine unattended.

C. Personal Safety Rules

- (1) Report any accident, however small, immediately it happens.
- (2) Wear safety glasses.
- (3) Wear safety shoes.
- (4) Use barrier creams provided.
- (5) Wear your overalls buttoned up.
- (6) Roll sleeves up, or button the cuffs.
- (7) Keep hair short or wear a cap.
- (8) Use the correct size spanners at all times.
- (9) Be careful of, and remove if possible, burrs and sharp edges.
- (10) Use the correct type of sling when lifting workpieces, of the correct safe working load and ensure it is not worn or damaged.
- (11) Stand clear when lifting workpieces or equipment by crane.
- (12) Obtain assistance when mounting heavy or awkwardly shaped workpieces.
- (13) **Do not** wear rings, watches, ties, etc.
- (14) **Do not** keep tools (scribers, etc.) in overall pockets.
- (15) **Do not** remove guards unless machine is stationary.
- (16) **Do not** wash hands in coolant.
- (17) **Do not** remove swarf with bare hands, use a rake or brush.
- (18) **Do not** manually lift heavy equipment.
- (19) **Do not** use files, scrapers, etc. without handles.
- (20) **Do not** lean on the machine.
- (21) **Do not** interfere with electrical equipment.

Maintenance




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

Changewheel Shear Pin (Fig. 1)

A protection against accidental overload in the end gear train is provided in the form of a shear pin fitted in the splined sleeve on the top changewheel shaft. In the event of replacement being necessary a 4 mm (5/32") diameter x 20 mm (3/4") long mild steel pin should be fitted as follows:-

Remove the hexagon nut, washer and changewheel, pull off the splined sleeve and remove the broken pin parts from both sleeves and shaft. Fit new pin.

NOTE: The pin acts in single shear and will only enter the sleeve from the 'big-hole' side.

Leadscrew Shear Pin (Fig.2)

A shear pin device is incorporated on the leadscrew adjacent to the gearbox, as protection against overload. Instructions for replacing the shear pin are as follows:-

Remove the torque limiter cover plate.

Disengage shear pin assembly by sliding away from gearbox face.

Rotate spring steel cover on its locating sleeve until access slot is exposed.

Release M5 dog-point set screw in sleeve and rotate sleeve and cover until shear pin is exposed through slot.

Replace shear pin as shown in illustration (2) and re-assemble ensuring that the dog point of the M5 set screw is correctly located.

Drive Belts (Fig. 3 and 4)

Access to the Drive Belt is gained by removal of the moulded end guard when vee Belt tension may be assessed by applying finger pressure on the belt at a point midway between the two pulleys (fig. 3). For correct tension a deflection of about 10 mm should be possible.

To adjust the vee belt tension – release the lock nut on the adjusting screw (fig. 4) to increase tension, tighten screw against the bed until correct tension is obtained then re-tighten lock nut.

It is important that when making adjustments a straight edge be placed across the face of each pulley to ensure that correct alignment is maintained.

Saddle Strips (Fig. 5 and 6)

Wear on the rear and front saddle strips may be accommodated by adjustment of the retaining sleeves located in the top face of the saddle; two for the rear and one each for the two front strips.

The procedure for adjustment is to first release the socket head screw, slightly turn the slotted head sleeve anti-clockwise and then re-clamp the cap screw. Care should be taken to avoid over adjustment; a 30° turn at the sleeve represents approximately 0.1 mm (.004") take up in the strip.

Tailstock Bed Clamp (Fig. 7)

The angular lock position of the bed clamp lever is adjusted by means of the self-locking hexagon headed bolt located on the underside of the tailstock and between the bed ways.

continued

Cross-slide (Fig. 8)

Wear on the taper-gib strip may be adjusted for by clockwise rotation of the slotted head screw on the front face of the cross-slide. The procedure being to first slacken the similar screw at the rear then re-tighten this after adjustment to clamp the strip in its new position.


Top Slide (Fig. 9)


Take up for wear on the top slide strip is by means of the four (self-locking) socket set screws in the front face of the top slide casting.

Cross-slide Nut (Fig. 10)

Provision is made for the elimination of backlash in the cross-slide nut, the procedure for adjustment being as follows:-

Release **only** the rear pair of socket cap head screws in the top face of the cross-slide, which allows a spring loaded device to automatically remove backlash. Re-tighten cap head screws.





The spindle bearing assembly is carefully set before despatch of the Lathe from our Works which should ensure a high standard of performance without the need for further attention.

THE USER IS ADVISED NOT TO DISTURB THIS SETTING DURING NORMAL USE OF THE MACHINE AND TO CONSULT OUR SERVICE DEPARTMENT IN THE UNLIKELY EVENT OF A BEARING PROBLEM.

WHERE ADJUSTMENT IS UNDERTAKEN THEN IT IS ESSENTIAL THAT THE FOLLOWING PROCEDURES ARE STRICTLY COMPLIED WITH.

TO CHECK FOR CORRECT SETTING

Checks should be carried out with the headstock in a warm condition achieved by running at a spindle speed of 800 rpm for approximately ten minutes.

The correct bearing torque setting is 0.9/1.1 Nm (8/10 in lbs) and can be determined as follows (Fig. 1):-

Wrap a length of string approximately three turns around the body of the chuck.

To the free end of the string attach a light spring balance and pull gently until spindle commences to turn, continuing to apply a steady load just sufficient to maintain the spindle in motion and noting the steady load registered on the balance.

Example: Using a 160 mm (6¼ in) chuck, the spring balance reading should be 1.14/1.36 kg (2½/3 lbs).

BEARING ADJUSTMENT

Remove end drive guard, changewheels, swing frame and rear bearing cover.


Release locking screw in the bearing adjusting nut, Fig. 2. With the pin-key provided adjust the nut as required - clockwise rotation to increase bearing load, Fig. 3. As over tightening will seriously impair the life of the bearings it is recommended that adjustment be made in increments not exceeding 3 mm (1/8 in) measured on the nut periphery. After each incremental adjustment, the spindle should be run for a few minutes and the bearing load re-checked, as described above.

Parts Ordering Procedure

1

**Quote:
Machine Serial Number**

which will be found stamped into the front face of the bedways at the tailstock end



2

Refer to the appropriate assembly and

**Quote:
Individual Part Numbers taken direct from the Illustrations**

NOTE: Quantity used (when other than one) is given in a circle following the Part Number itself.

Where part numbers change with machine bed length then the model number is given, vis.

500

or



750

Standard/Proprietary Parts (i.e. items which can be purchased from local Engineering suppliers) may be identified by the "bracketed" letter code included in the Part Number, and reference to the appendix at the end of this manual will provide a full description of such items.

Parts Section

Contents List


		Page No.
901/1	Bed and cabinet	25
901/2	Drive	26
901/3	Changewheel guard	27
902/1	Headstock	28
902/2	Headstock gears	29
902/3	Headstock controls	30
903/1	Gearbox casting and shafts	31
903/2	Gearbox gears and shafts (Metric)	32
903/3	Gearbox gears and shafts (English)	33
904/1	Apron casting and controls	34
904/2	Apron shafts	35
905/1	Saddle	36
905/2	Slides	37
906	Shafts, rack and bracket	38
907	Tailstock	39
908	Changewheels and swing frame	40
910	Standard equipment	41
911	Additional equipment (see section list)	42
912	Taper turning attachment	56
913	Bed capstan unit	57



*911001(500mm)
911002(750mm)

7/1908 *
(WILMOT BREEDON)

901/1



KEY TO DRIVE ASSEMBLY COMPONENTS (901/2)

1

2


3

4

5


6

MOTOR		TOP SPEED SPINDLE	TOP PULLEY	MOTOR PULLEY	KEY	MOUNTING BRACKET	BELTS
D80	3 PH 50Hz	1500 3000	902010	901012	6x5x40 (KR)	901007	SPZ 800
D90S	Single PH 50Hz	1500	902053	901023	8x7x32 (KR)	901037	NU-T-Z/10(40°) Brammer ②
D80	3 PH 60Hz	1500 3000	902010	901028	6x5x40 (KR)	901007	SPZ 800
LS145T	3 PH 60Hz	1500	902010	901013	3/16"x3/16"x1.3/8"(KS)	901008	SPZ 800
LS145T	3 PH 60Hz	2000	902057	901026	3/16"x3/16"x1.3/8"(KS)	901008	SPZ/3V 787
EL145T	Single PH 60Hz	2000	902061	901033	3/16"x3/16"x1.3/8"(KS)	901008	SPZ/3V 787
EL145T	Single PH 60Hz	1500	902089	901051	3/16"x3/16"x1.3/8"(KS)	901008	SPZ 800




1035 - METRIC THREAD ENGLISH GEARBOX
 1145 - ENGLISH THREAD METRIC GEARBOX


1037 (METRIC)
 1140 (ENGLISH)




901/3


902/1








902/3




metric




903/2

english


903/3




904/1




AVAILABLE AS
 ADDITIONAL
 EQUIPMENT
 *




904/2




905/1



905/2




906



*ITEMS SUPPLIED AS ADDITIONAL EQUIPMENT

907




STANDARD

- 22T - 908.022
- 40T - 908.040
- 44T - 908.044
- 80T - 908.080
- 88T - 908.088
- 92T - 908.092


OPTIONAL

- 21T - 908.021
- 24T - 908.024
- 28T - 908.028
- 30T - 908.030
- 35T - 908.035
- 42T - 908.042
- 45T - 908.045
- 48T - 908.048
- 49T - 908.049
- 55T - 908.055
- 56T - 908.056
- 60T - 908.060
- 63T - 908.063
- 66T - 908.066
- 70T - 908.070
- 72T - 908.072
- 76T - 908.076
- 78T - 908.078
- 81T - 908.081
- 84T - 908.084
- 98T - 908.098
- 99T - 908.099
- 100T - 908.100


908




M8/13mm x 15mm (WRS)
 M10/17mm x M12/19mm (WRS)
 M14/22mm x M16/24mm (WRS)
 M18/27mm x M22/32mm (WRS)




TH15



63mm
(SPINDLE NUT)




910009




L5-585A

910001



910006




2.5mm (FK)
 3mm (FK)
 4mm (FK)
 5mm (FK)
 6mm (FK)
 8mm (FK)

D101H2094

M12x25
(FY)


D220H1013



M6x12 (FY) ③

910005 ③

F60
(OIL GUN)




910

Additional Equipment


		Page No.
911.09	American Toolpost	42a
911.10	4-way hard-indexing toolpost	43
911.11	Quick-change toolpost	44
911.12	Quick-change parting off toolholder	44
911.14	Chuck guard assembly	45
911.31	Saddle mounted chip guard	46
911.32	Perspex chip guard-magnetic base	47
911.35	Coolant pump tank and fittings	48
911.38	Low-voltage machine light	49
911.41	Travelling steady	50
911.42	Stationary steady	51
911.45	5-position stop-cross-slide traverse	52
911.46	Single stop - saddle traverse	52
911.47	Micrometer stop - saddle traverse	52
911.48	5-position stop - saddle traverse	52
911.60	Magnetic based dial indicator - Metric graduations	47
911.61	Magnetic based dial indicator - English graduations	47
911.67	Thread dial indicator assembly	53
911.81	Emergency foot switch	54

Parts available as assemblies (not illustrated):

911.65	Metric/English dual reading dial - Cross-slide (English cross-slide screw and nut required)	
911.66	Metric/English dual reading dial - Topslide (English topslide screw and nut required)	
911.72	Wattmeter	
1542-21601	4-jaw chuck	
1212-21305	3-jaw chuck	
D911H007.1	Faceplate	




911/09





911/10

911/11




911/12







911/14





911/31

911/32




911/60-61







911/38




911/41



911/42





911/46




911/47



911/48



911/45




911/67




911/81

Attachments

	Page No.
912 Taper turning attachment	56
913 Bed capstan unit	57



912



* Ø 20MM - METRIC
 Ø 3/4 - ENGLISH

913

Standard/Proprietary Parts

Letter Codes

'Bracketed'
Letter Code

Component

Conventional
Description Given

Screws and Nuts

FX	Socket Set (Grub) Screw: Flat Point
FXd	" " " " Dog Point (Normal)
FXd1	" " " " Dog Point (Long)
FXc	" " " " Cone Point
FXw	" " " " Cup, knurled or 'W' Point

Thread X O/all Length

" " " "
" " " "
" " " "
" " " "

FY	Socket Head Cap Screw
FY1	Socket Head Cap Screw (Threaded to Head)
FV	Socket Countersunk Screw
FS	Socket Button Head Screw

Thread X Length under head

" " " "
" " " "

FU	Socket Shoulder Screw
----	-----------------------

Thread X Ø Shank X Shank length

FP	Socket Pressure Plug
FPS	Press Plug (Square Head)

Thread and Form

" "

FO	Slotted Set (Grub) Screw
----	--------------------------

Thread X O/all Length

FT	Slotted or Pozidriv Screw: Countersunk Head	
FI		" " " " Raised C/sunk Head
FR		" " " " Pan Head
FE		" " " " Cheese Head

Thread X length under head

" " " "
" " " "

Suffix 'B' for Thread Forming Type
Suffix 'T' for Thread Cutting Type
Suffix: 'SS' for Stainless Steel

FJ	Square Head (Toolpost) Screw
FH	hexagon Head Screw
FD	" " Bolt
FN	Standard Hexagon Nut
FL	" " " Locknut
	Suffix '8.8' for High Tensile Types

Thread X Length under head

Thread X Length under head

" " " "
" " " "
" " " "

Suffix 'L' for 'Self-Locking' versions of the above

FZ	Hammer Drive Screw
----	--------------------

Nom Ø X Length under head

FW	Wing Nut
----	----------

Thread details

DN	Domed Nut
CN	Castle of Slotted Type Nut
FN1	Nylon Ring Locking Nut

Thread details

" "
" "

Thread Inserts

TI1	Press in Type Thread Insert
TI2	Coil Type Thread Insert

Thread details

" "

Washers

WN	Bright Washer: Normal Diameter
WL	" " Large Diameter
WK	Crinkle (Wavy) Washer
WS	Spring Washer: Single Coil
WSs	" " Double Coil
WC	Folded Copper Sealing Washer
WF	Felt Washer
DS	Disc Spring (Belleville Washer)

Nominal Hole Ø

" "
" "
" "
" "
" "
" "
" "

Nom. Hole Ø X O.D. X thickness

'Bracketed' Letter Code	Component	Conventional Description Given
Pins and Dowels		
GP1	Grooved Pin: Full length groove — Tight at one end	Nom. \emptyset X O/all length
GP2	" " Half length groove — Tight on end	" " "
GP3	" " Full length groove — Parallel	" " "
GP4	" " Half length groove — Tight at centre	" " "
GP5	" " Centre groove	" " "
PD	Dowel Pin	Nom \emptyset X O/all length
PB	Brass Pin or Pad	" " "
PT	Taper Pin	Nom \emptyset (small end) X O/all length
PS	Split Pin	Nom \emptyset X O/all length
LTP	Tension Pin: Light Duty	Nom \emptyset X O/all length
HTP	" " Heavy Duty	" " "
Keys		
KS	Square Parallel Key	Width X Thickness X Length
KR	Rectangular Parallel Key	" " " "
KW	Woodruff Key	Width X Height X Diameter
Circlips		
CE	External Circlip: DIN 471	DIN. Ref. Nom Shaft \emptyset and Thickness
CE1	Round Section Circlip	Nom. Shaft \emptyset , Wire \emptyset
CE2	Inverted Retainer (Truarc)	" " "
CB	Internal Circlip: DIN 472	DIN. Ref. Nom Bore and Thickness
CR	Radial Fitting Circlip. DIN 6799	DIN Ref. Nom \emptyset and Thickness
CR1	Radial Retaining Clip (Spring fix)	Nom shaft \emptyset
CR2	Radial Fitting Circlip BS3673/3	" "
Plain Bearings		
DU	Composite Bearing Bush 'Glacier'	Nom Bore. O.D. and Length
DX	" " " " "	" " " "
LB	Sintered Bronze Bush	Nom Bore O.D. and Length
Ball & Roller Bearings		
BB	Std. Ball Bearing	Nom Bore Outside \emptyset and Leng
BB1	Std. Ball Bearing with Shield or Seal one side	" " " " "
BB2	Std. Ball Bearing with Shield or Seal both sides	" " " " "
BB3	Std. Ball Bearing with Snap Ring	" " " " "
BBT	Angular Contact Ball Bearing	" " " " "
RB	Cylindrical Roller Bearing	" " " " "
For Needle Roller Brgs, Needle Thrust Races Ball Thrust Brgs. and Taper Roller Bearings — Manufacturers Name is Quoted as Letter Code — vis.		
(INA.)	(TORRINGTON)	Manufacturers Part No. Quoted
(SKF)	or (GAMET)	

**'Bracketed'
Letter Code**

Component

**Conventional
Description Given**

Seals

SM	Standard Oil Seal
SF	'V' Ring Seal (FORSHEDA)
RM	Standard 'O' Ring Seal
RM1	'Nu-Lip Ring' (Pioneer)

Nom Shaft Ø O.D. and Width
Manufacturers Part No.
Internal Ø of Ring, and Section Ø
Manufacturers Part No.

Lubrication Equipment

ON	Concave Oil Nipple: Drive in Type
ONI	" " " Threaded Type
OS	Oil Sight Glass
OS1	Oil Level Glass
OW	Oil Wick

Nom Hole Ø
Thread details
Nom Outside Ø
" "
Nom Ø X Length

For Compression and other Pipe Fitting — Manufacturers Name is quoted as Letter Code vis.

(ENOTS.)
or (TECALEMIT)





Manufacturers Part Number
Quoted

Miscellaneous Items

BJ	Ball Joint
SB	Steel Ball
FK	Hexagon Wrench Key
HP	P.V.C. Hose
HC	Hose Clip
PP	Plastic Plug
WRS	Standard Spanner
EB	Eye Bolt
OW	Oil wick
CT	Copper tube
NT1	Nylon Tube Natural
NT2	Nylon Tube Blue
NT3	Nylon Tube Green
NT4	Nylon Tube Red


Thread Details
Nom Ø
Nom width across flats
Nom Bore and O.D.
Max. Hose Ø
Manufacturers Part Number
Std. Bolt size and width
across flats
Thread details
Nom Ø X Length
Nom outside Ø
Nom Bore
" "
" "

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1Q	Main disconnect switch	All	Klockner Modifer	P1-25
1K1M	Motor	All	Yokohama	HE-152
1F2	Overload relay	380V 415V 220V	Yokohama	RH-1014K
1T	Control circuit transformer	All	Romarch or alt	220V/380V 415&440V Wye wye with 110V & 170V secondary & VA
1S	Reverse switch	All	Klockner Modifer	T1-3-2
2S	Coolest on off switch	All	Klockner Modifer	T1-3-50
3S	Start pushbutton (main motor)	All	Klockner Modifer	BK-12
1X	Terminal Block	All	Klaxon	BK-12
2X	Terminal Block	All	Klaxon	BK-12
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To 415 supply voltage	GEC	6500 90 w/ft 2hp 1500 RPM
5S	Guard limit switch	All	Burgess	KE 5E0R
7S	Kick stop limit switch	All	Burgess	KE 5E0R
2M	Coolant pump motor	All	MG Electric	MA 12448S
1E	Machine light unit 2 arm fitting (400-400)	All	MG Electric	ADD20
2T	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MGL 4025 BOSA
	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MGL 4040 BOSA
	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MST 600
	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MST 600
	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MST 600
	Transformer unit 25V (210/230/250)	25V (400-400) 25V (210/230/250)	MG Electric	MST 600
1P	Wattmeter	50V (500/550)	Complan Intl.	057-218B






EWD 901.1 Standard
220/380/415 V 3PH 50Hz
1500 RPM m/c / 0.9Kw Motor

Wiring Diagram



KEY & COMPONENT LIST	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1Q	Main disconnect switch (lockable)	All	Klockner Moeller	F1-25
1K1M	Main contactor	All	Yaskawa	HE-6S5
1F2	Overload relay	380V/415V 220V	Yaskawa	RH-102DK RH-102DK 200-80V/415/640V Primary with 110V & 12V Secondary @ VA T1-3.2 T1-3.60
1T	Control circuit transformer	All	Powernorth or #H	
1S	Reverse switch	All	Klockner Moeller	
2S	Forward on/off switch	All	Klockner Moeller	
3S	Stop switch	All	Klockner Moeller	
4S	Stop pushbutton (main motor)	All	Klockner Moeller	
1X	Terminal Block	All	Kilgus	BK-12
2X	Terminal Block	All	Kilgus	BK-12
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To suit supply voltage	QEC	D905/1.5Kw/2 HP 1500 RPM
5S	Guard limit switch	All	Burgess	KB 5E0R
6S	Kick stop limit switch	All	Burgess	KB 5E0R
7M	Machine pump motor	All	IMI V3HIMS	IMI V3HIMS
1E	Machine light unit (2 arm fitting 1000x400)	All	ADZED	ADZED
2T	Transformer unit 50V (D18/14/440) 50V (D10/20/250) 50V (B50/550)	All	MG Electrica	MGL 4040 B05A MGT 60A MGT 60B MGT 60C MGT 60E MGT 60E 067-216B
1P	Watermeter		Crompton Inlet	




EWD 901.1A Standard
220/380/415 V 3PH 50Hz
2000 RPM m/c / 1.5Kw motor

Wiring Diagram

KEY AND COMPONENT LIST


REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1Q	Main disconnect switch (isolator)	All	Klockner Moeller	P1-25
1K1M	Machine motor	All	Yaskawa	HE-185
1F2	Chuck stop limit switch	All	Yaskawa	RH-107/K
1T	Control circuit transformer	All	Romark or alt	240V P T1-3-2 T1-3-2 T1-3-2 T1-3-2 T1-3-2 T1-3-2
1S	Reverse switch	All	Klockner Moeller	
2S	Coasting on off switch	All	Klockner Moeller	
3S	Start pushbutton (main motor)	All	Klockner Moeller	
4S	Stop pushbutton (main motor)	All	Klockner Moeller	
1X	Terminal block	All	Klappan	BK-12 BK-12
2X	Terminal block	All	Klappan	BK-12 BK-12
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To, with supply voltage	GEC	D 905/1.1/1.5
5S	Guard limit switch	All	Burgess	KBS EDR
6S	Chuck guard limit switch	All	Burgess	BS 100
7S	Kick stop limit switch	All	MG Electric	MG 371/IE
8S	Machine light switch	All	MG Electric	MG 371/IE
1E	Machine light unit 2 arm fitting (400-250)	All	MG Electric	MGL 4025 BOSA
2T	Transformer unit 10V (machine light) 28V	All	MG Electric	MGL 4040 BOSA



EWD 903.1 Single phase
240V 1PH 50Hz



*When fitted

Wiring Diagram




KEY AND COMPONENT LIST

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1MCS	Mains disconnect switch (Isolator)	All	Klockner Moeller	T1-2-NA
1M	Main contactor	All	Yaskawa	HE-16S
10L	Overload relay	230V	Yaskawa	RH-10/5K
		460V	Yaskawa	RH-10/3K
1T	Control circuit transformer	All	Romarch or alt	ULF(UF/25/3 208 230 460 575 Volt primary 115 Volt secondary at 25VA T1-3-2 T1-3-50
1RS	Reverse switch	All	Klockner Moeller	
1S	Coolant on off switch	All	Klockner Moeller	
1PB	Start pushbutton (main motor)	All	Yaskawa	
2PB	Emergency stop pushbutton	All	Yaskawa	
1&2TB	Terminal block	All	Klippon	BK 12
MACHINE MOUNTED COMPONENTS				
1MTR	Main motor	To suit supply voltage	Brook	K145T, 1 1/2 HP, 1800RPM
1LS	Guard limit switch	All	Burgess	K85 EOR CSA/UL
2LS	Chuck guard limit switch	All	Burgess	K85 EOR CSA/UL
3LS	Kickstop limit switch	All	Burgess	(MIV)3HM6S CSA/UL
2MTR	Coolant pump motor	To suit supply voltage	MG Electric	AQ3/2




*When fitted



EWD 905.1 U.S.A.
230-460V 3PH 60Hz



Wiring Diagram



KEY AND COMPONENT LIST

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
MCS	Main disconnect switch (handle)	All	Klockner Moduler	T1-25 NA
1M	Main motor	All	Yeskawa	HE-165
10L	Overload relay	All	Yeskawa	RH-107DK
1T	Control circuit transformer	All	Romarch or alt	220V primary with 220V secondary
1RS	Reverse switch	All	Klockner Moduler	T1-2-2/NA
1S	Constant on/off switch	All	Yeskawa	T1-2-50/NA
1PB	Start button	All	Yeskawa	
2PB	Stop button (handle)	All	Yeskawa	
1&2TB	Terminal block	All	Klippon	BK-12
MACHINE MOUNTED COMPONENTS				
1MTR	Main motor	All	Brook	K145T, 1HP
1LS	Guard limit switch	All	Burgess	100000000 CSA/U/L
2LS	Check guard limit switch	All	Burgess	KBS EDR CSA/U/L
3LS	Kickstop limit switch	All	Burgess	IMI V2HMBS CSA/U/L
2MTR	Coilant pump motor	All	M G Electric	ADJ2 CSA/U/L

*When fitted



EWD 907.1 Single Phase U.S.A.
220/1/60Hz

Wiring Diagram